Approved For Release 2009/07/07 : CIA-RDP78B03817A000500010061-2

CONFIDENTIAL

OUT61765

1967 APR 18 04 53Z

18 APR 1967

P 180421Z APR 67

FM NPIC WASH DC

TO AIG NINE SEVEN SIX

RUEPJS/DIA PRODCEN

RUEPJS/NIC

BT

C O N F I D E N T I A L CITE NPIC 0430.

CPIR:NPIC SER:F00229 UEYT MSN:00205K 27MAR67H

DAY PHOTO. CAMERA ON/OFF TIMES UNK. REF NPIC MSG 8140, DTG 180235Z, AUG 66. AMS SERIES L7014, SHEETS 6144 I, 6145 II, 1ST ED.

DISTRIBUTION		
Cy No.	Office	Action
1	File	
2	OS	
	SFC BR	
	TDS	
3	CSD	
	IFD	
4	PD	
	PSD	
	PSD-ICB	
	TID	
5	IAD	
6	PAG	
	DIA	
7	SPAD	*
	NSA-LO	
	DIA-AP	

Advance copy

* Sanitized

Seen by D E/D S/A 4/18/67

PART I. SIGNIFICANT PHOTO INTERPRETATIONS

B. NEW TARGETS AND SIGNIFICANT CHANGES

ITM01:RR BY-PASS & CABLE BR U/C SGM:UNK CTY:VN 175713N1055752E

DES:A NEW RAILROAD BY-PASS AND A CABLE BRIDGE ARE UNDER CONSTRUCTION AROUND THE SERVICEABLE KIM LU XA RR BRIDGE [redacted] OVER THE KHE DANH (STREAM) ON THE VINH/DONG HOI RAIL LINE. T-SHAPED CABLE ANCHORAGE EXCAVATIONS ARE LOCATED IN LINE WITH 3 A-FRAME AND 4 CRIB WOODEN SUPPORTS ACROSS THE STREAM AT UTM XE021851. DECK FRAMEWORK WITHOUT TIES OR RAILS IS LOCATED IN LINE WITH THE SUPPORTS ON THE EAST BANK. THE CABLES WILL PROBABLY BE USED TO HELP SUPPORT

25X1

CONFIDENTIAL

Excluded from automatic downgrading and declassification

Approved For Release 2009/07/07 : CIA-RDP78B03817A000500010061-2

Approved For Release 2009/07/07 : CIA-RDP78B03817A000500010061-2

THE DECKING, TO STABILIZE THE WOODEN SUPPORTS, AND TO SERVE AS GUY CABLES TO EMPLACE OR REMOVE THE DECKING.

[redacted] 25X1

ITM02:RR BY-PASS/PROB CABLE BR U/C SGM:UNK CTY:VN 175832N1055553E

DES:A RAIL ROAD BY-PASS AND A PROBABLE CABLE BRIDGE, SIMILAR TO THE ONE DESCRIBED IN ITEM 1, ARE UNDER CONSTRUCTION SOUTH OF THE DESTROYED XOM KHE RAILROAD BRIDGE [redacted] 25X1 OVER THE KHE NET (STREAM). SEVERAL WOODEN SUPPORTS/PIERS HAVE BEEN ERECTED AND THE PARTLY ASSEMBLED DECK FRAMEWORK IS LOCATED NEAR THE MAIN LINE AT WE983879. ONLY THE CABLE ANCHORAGE EXCAVATION ON THE EAST STREAM BANK WAS OBSERVED. NO TIES OR RAILS HAVE BEEN LAID. THE RAIL BY-PASS AND BRIDGE NORTH OF THE MAIN BRIDGE REMAIN SERVICEABLE.

[redacted] 25X1

PART II. OTHER PHOTO INTERPRETATIONS - NONE

GP-1

C O N F I D E N T I A L

((NOTE: ABOVE MESSAGE ALSO PASSED PRIORITY SAIGON INFO DIRECTOR, VIENTIANE, UDORN AS NPIC 0430)) END OF MESSAGE

Approved For Release 2009/07/07 : CIA-RDP78B03817A000500010061-2